





<b>Project Name:</b> Gold King Mine – September 11, 2014	<b>Site Location:</b> Silverton, San Juan County, Colorado	<b>Project No.</b> NA
---	---	--------------------------

<b>Photo No.</b> <b>1</b>	<b>Date:</b> 09/11/2014	
<b>Direction Photo Taken:</b>  North		
<b>Description:</b>  Gold King Mine prior to 2014 site work. Photo taken on 9/11/2014 at 12:37 pm prior to start of work. 3-inch Parshall flume is at the right of the photo, in the plastic structure.		

<b>Photo No.</b> <b>2</b>	<b>Date:</b> 09/11/2014	
<b>Direction Photo Taken:</b>  East		
<b>Description:</b>  Gold King Mine prior to 2014 site work. Photo taken on 9/11/2014 at 12:28 prior to start of work. Low flow in discharge channel.		



<b>Project Name:</b> Gold King Mine – September 11, 2014	<b>Site Location:</b> Silverton, San Juan County, Colorado	<b>Project No.</b> NA
---	---	--------------------------

<b>Photo No.</b> <b>3</b>	<b>Date:</b> 09/11/2014	
<b>Direction Photo Taken:</b>  South		
<b>Description:</b>  Gold King Mine 3-inch Parshall flume. Note low flow in channel. Photo taken on 9/11/2014 at 12:42 prior to the start of work. Water is at 0.1 feet, which corresponds to 12.55 gallons per minute flow.		

<b>Photo No.</b> <b>4</b>	<b>Date:</b> 09/11/2014	
<b>Direction Photo Taken:</b>  South		
<b>Description:</b>  Gold King Mine 3-inch Parshall flume. Note low flow in channel. Photo taken on 9/11/2014 at 12:42 prior to the start of work. Water is at 0.1 feet, which corresponds to 12.55 gallons per minute flow.		



<b>Project Name:</b> Gold King Mine – September 11, 2014	<b>Site Location:</b> Silverton, San Juan County, Colorado	<b>Project No.</b> NA
---	---	--------------------------

<b>Photo No.</b> <b>5</b>	<b>Date:</b> 09/11/2014	
<b>Direction Photo Taken:</b>  Northwest		
<b>Description:</b>  Small amount of flow from side adit approximately 100 feet west of main adit/flume. Photo taken on 9/11/2014 at 12:53.		
<b>Photo No.</b> <b>6</b>	<b>Date:</b> 09/11/2014	
<b>Direction Photo Taken:</b>  Northwest		
<b>Description:</b>  Start of 2014 excavation work. Photo taken on 9/11/2014 at 16:10.		